

ASSOCIATION OF VILLAGE COUNCIL PRESIDENTS

# Public Safety FACILITIES ASSESSMENT

Summer of 2018



[AVCP.ORG](http://AVCP.ORG)

PO BOX 219 BETHEL, AK 99559



## OVERVIEW

This document includes information collected by the Association of Village Council Presidents (AVCP) Public Safety Facilities Assessment team.

Throughout the months of May and June of 2018, this team conducted site visits of 46 villages in the Yukon-Kuskokwim Delta, also known as the AVCP Region.

The conditions of public safety buildings varied greatly.

Eight communities did not have a public safety facility of any kind. They are listed on page 4.

All aggregated information is found on pages 7-9.

Beginning on page 11, this document outlines each community surveyed, organized by AVCP units, with photos of areas in need of repair.

Every page identifies the top three to five critically necessary repairs to each public safety building. (It is by no means an exhaustive list.)

Critically necessary repairs to public safety housing, were also recorded, when possible.

## POINTS OF FOCUS

Facilities assessed in each community included:

1. Public Safety Building
2. Public Safety Housing  
(available to public safety officers)

When accessible, the following facility features were inspected and photographed.

- Foundation
- Posts & Pads
- Water & Sewer Lines
- Entrance
- Steps
- Egress Windows
- Siding
- Roof
- Chimmney
- Meter Bases
- Vents
- Electrical Service Entrances
- IT infrastructure

## TRAVEL

As all communities within the AVCP region are not connected to the road system, site visits were restricted to air and water travel. Once staff reached the sites, they relied on contacts made prior to arrival.

On average, three communities were assessed for each day of travel.

## THE TEAM

The traveling team was lead by the AVCP Director of the Village Public Safety Officer Program, Alvin Jimmie, and Administrative Assistant, Edna Woods. With very little exception, they were always accompanied by at least one staff member from each of the following departments.

- Facilities
- Administration
- Communications
- Information Technology (IT)

Note: Staff are not licensed to conduct building inspections. Therefore, regardless of any description found herein, AVCP in no way represents or warrants that any facility is in a safe and habitable condition, and/or is suited to house public safety activities.

# CONTENTS

## Action items by community

### UNIT 1

Kotlik ... pg. 10

### UNIT 5

Napakiak ... pg. 26

Napaskiak ... pg. 27

### UNIT 9

Chevak ... pg. 42

Hooper Bay ... pg. 43

Scammon Bay ... pg. 44

### UNIT 2

Mountain Village ... pg. 12

Pitka's Point ... pg. 13

Saint Mary's ... pg. 14

### UNIT 6

Atmautluak ... pg. 28

Kasigluk ... pg. 29

Nunapitchuk ... pg. 30

### UNIT 10

Eek ... pg. 45

Goodnews Bay ... pg. 46

Platinum ... pg. 47

Quinhagak ... pg. 48

### UNIT 3

Aniak ... pg. 15

Chuathbaluk ... pg. 16

Upper Kalskag ... pg. 17

Lower Kalskag ... pg. 18

Lime Village ... pg. 19

Red Devil ... pg. 19

Sleetmute ... pg. 20

### UNIT 7

Kipnuk ... pg. 31

Kongiganak ... pg. 32

Kwigillingok ... pg. 33

Tuntutuliak ... pg. 34

### UNIT 11

### UNIT 12

Marshall ... pg. 49

Pilot Station ... pg. 50

Russian Mission ... pg. 52

### UNIT 4

Akiakchak ... pg. 22

Akiak ... pg. 23

Kwethluk ... pg. 24

Tuluksak ... pg. 25

### UNIT 8

Chefornak ... pg. 35

Mekoryuk ... pg. 37

Newtok ... pg. 38

Nightmute ... pg. 39

Toksook Bay ... pg. 40

Tununak ... pg. 41

### UNIT 13

Alakanuk ... pg. 53

Emmonak ... pg. 55

Nunam Iqua ... pg. 56

## No public safety facilities of any kind



Crooked Creek  
Chuathbaluk

Lime Village  
Oscarville



Pitka's Point  
Platinum

Red Devil  
Stony River

# POPULATION



# CRIME PER CAPITA



Village	Approx. Population	Crime Per Capita	Village Public Safety Officer (VPSO)	Tribal Police Officer (TPO)	Village Police Officer (VPO)	Public Safety Building	Action Items - Public Safety Building	Housing Availability	Action Items - Housing	Established Tribal Court	Dedicated Tribal Court building? YES/NO
Akiachak	627	0.079	0	5	0	Renovated 2011/2012; TPO'S uses the building		Yes, Chief of PD uses it		Very active tribal court, three judges	YES - has separate building for Tribal Court
Akiak	400	0.0803	0	2	0	In progress for building	(1) Needs holding cell (2) Water & Dwer needs to be turned back on (3) Prch & Stairs (4) Window	Yes		Has an active tribal court but is still in the beginning stages and is looking to forms that they are missing and how they will be able to file small claims for people who do not pay their PC fines.	YES - currently under construction with corporation
Alakanuk	734	0.043	0	0	2	Adequate public safety building, recently renovated	(1) Heater repair/replace (2) Foundation repair/replace (3) No running water (4) Leaking fuel line (5) Soffit missing (6) broken windows & doors (7) Electrical panel service & cover	Yes	(1) Front stairs & deck (2) Windows broken (3) Ground rod (4) Foundation	"In Process"	NO - sharing Tribal Council office
Aniak	522	0.1907	0	0	0	Built a 12x16 public safety building some years ago	(1) Insulate Floor (2) Hook up plumbing (3) Insulate water & sewer lines	Yes, with City		Has a tribal court but is just beginning with it.	NO - shared office space
Atmauthluk	300	0.0504	0	2	3	Renovated sometime in 2011/2012; VPSO'S uses building	(1) Window (2) Flooring (3) Chimney (4) Entry Stairs (5) Fuel leak	No		Has an active courts with 1 judge	NO - using Tribal Council office
Bethel	6378	unknown	1 Roving VPSO, based in Bethel	Bethel Police Department	0	Bethel Police Department has building		No		Orutsarmiut (ONC) - has an active tribal court .	NO - shared office space
Chauthbaluk	111	unknown	0	0	0	N/A		None		"In Process"	
Chefornak	500	0.0305	0	2	0	Renovated 2011/2012; VPO or TPO using building	(1) Electrical panel/meter base (2) Plumbing (3) Front entrance deck & stairs (4) Broken window	Yes, Under the City Council	(1) Exposed electrical wire (2) Foundatio (3) Fuel tank stand (4) Missing chimney cap	Chefornak- has an active tribal court	YES - they have their own office in corporation building
Chevak	1064	0.03	0	0	12	Renovated 2011/2012; VPO/TPO using the building	(1) Boiler service and/or replacement (2 new biolers located in crates under building ) (2) Electrical pael service & repair (3) Exterior hand railing repair	Yes		None	
Crooked Creek	105	Unknown	0	0	0	N/A		No		None	
Eek	396	0.0404	0	1	1	Renovated 2011/2012; VPO/TPO using the building	(1) Foundation (2) Uninsulated floor (3) Broken window	None		None	
Emmonak	1020	0.1809	2	0	1	Good Condition; VPSOS & VPO using the building; adequate jail cell	(1) Broken front door glass (2) Exterior paint	Yes		Emmonak- has an active tribal court	YES - has their own building at the old courthouse
Goodnews Bay	253	0.0308	1	0	0	Renovated 2011/2012 May, needs jail doors replaced		No, the VPSO has his own house.		None	
Hooper Bay	1200	0.0808	0	4	0	Renovated 2011/2012, VPO'S using the building	(1) Sewer line replacement (2) Miller Furnace (heater) maintenance (3) Broken windows & doors (4) Replace rear entry steps (5) Foundation level, repair, and/or replacement	Yes		Has active tribal court, court is hearing cases.	NO - shared office space
Kasigluk	600	0.0302	0	6	0	Inaccessible		No		Has an active tribal court	YES - Tribal Court building is connected to the Jail
Kipnuk	795	0.0304	0	3	0	Renovated 2011/2012	(1) Foundation (2) Broken window (3) Meter base service wire	Yes		Has an active tribal court, fully staffed	NO - separate office in Tribal Council building

Village	Approx. Population	Crime Per Capita	Village Public Safety Officer (VPSO)	Tribal Police Officer (TPO)	Village Police Officer (VPO)	Public Safety Building	Action Items - Public Safety Building	Housing Availability	Action Items - Housing	Established Tribal Court	Dedicated Tribal Court Building? YES/NO
Kongiganak	657	0.0301	0	3 (2 on-call)	0	Renovated 2011/2012, TPO'S using the building	(1) No heat (2) No running water (3) Broken Windows	No		Has an active tribal court	NO. Shared office space with Environmental department
Kotlik	640	0.0409	0	0	1	Condition of the building is unknown	(1) Broken window (2) Repair Entrance door (3) Exit door	Renovating.	(1) Raise building above flood level (2) Doors for bedrooms (3) Repair light fixture (4) Install flooring (5) Heating system service & repair	In Process of Re-establishment	
Kwethluk	751	0.0504	1	2 + 1 TPO Chief of Police	1	Built mid. 2000's. VPO'S also use the building. Requesting renovation	(1) Boiler repara (2) Reinforce cell door (3) Sew line inspection	Yes		Active Tribal Court	NO
Kwigillingnok	321	0.0202	0	4	0	Built a 12x16 building several years ago; requested installization of water/sewer system in building		No, need to be renovated		Has an active tribal court, all of their codes need updating but they do hear cases.	NO - shared office space
Lime Village	12		0	0	0	None		None		None	
Lower Kalskag	309		0	1	0	None	(1) Partition walls (2) Holding Cells (3) Doors & Windows	Tribal housing could be used.		Established	
Marshall	440	0.0705	0	0	1	Renovated 2011/2012	(1) Broken/missing windows (2) Foudnation repair/replacement (3) Roof metal repair / replace (4) Electrical hazards (5) Heater service/replacement	Yes		"In process"	
Mekoryuk	212	0.0505	1	2 + 1 on-call	0	Built a 12x16 building some years ago; VPO also uses building		No		Established	
Mtn Village	851	0.0701	0	0	1	None		Yes, 2 duplexes	(1) Broken window	Asa'carsarmiut (Mountain Village)- has an active tribal court	NO
Napakiak	380	Unknown	0	2	0	Good	(1) Window (2) Door lock (3) Exterior Stairs	Yes		"Not at the moment"	NO - sharing Tribal Council office
Napaskiak	450	0.03	1	2	3	Fair. Back door needs repairs. Requires new heater.	(1) Fron door was set on fire (2) Back door was set on fire (3) Foundation (4) Entry Steps	Yes		Not fully staffed trying to get tribal judges	
Newtok	374	0.0405	0	0	3	Currently at the village council office-space room		No		"In Process"	
Nightmute	316	0.0103	0	0	1	Exsits, VPO uses building		No	(1) No running water (2) No heat (3) Electrical panel / meter base service wire	None	
Nunam Iqua	196	0.1102	0	0	0	Unsanitary & unsafe; VPSO'S that go out for TDY uses the building.	(1) Mold & foul odor (2) Extensive water damage (3) Foundation (4) Stairs	No		Established	
Nunapitchak	650	0.0702	0	Yes + 3 judges	0	None		Jail cells were renovated, newer housing to be transformed to Public Safety			
Pilot Station	651	0.0306	0	0	3	Condition of the building is unknown	(1) Broken window (2) Broken/missing doors (3) Repair/replace Exterior Handrails (4) Needs finish flooring	Yes	(1) No sairs at second exit (2) Electrical panel cover (3) Entry Door Finish	None	

Village	Approx. Population	Crime Per Capita	Village Public Safety Officer (VPSO)	Tribal Police Officer (TPO)	Village Police Officer (VPO)	Public Safety Building	Action Items - Public Safety Building	Housing Availability	Action Items - Housing	Established Tribal Court	Dedicated Tribal Court Building? YES/NO
Pitkas Point	125	0.16	0	0	0	Adequate building		No		Unknown	
Platinum	64	0.0809	0	0	0	No adequate building due to land issues.		No		None	
Quinhagak	699	0.05	0	6	0	New, extraordinarily good condition; VPO/TPO's uses building		Yes		Quinhagak- has an active tribal court	NO
Red Devil	16	0	0	0	0	None		No		None	
Russian Mission	331	0.1109	0	0	0	Built 12x16 building some years ago, used for TDY VPSO. maintained	(1) Cable end metal missing	Yes		None	
Scammon Bay	600	0.0503	1	0	3	Renovated 2011/20012, needs remodeling	(1) Level/replace foundation (2) Inadequate size for personnel & equipment (3) Electric unit heater hazard (4) Building separating at prior addition (5) Broken windows	No		None	
Sleetmute	92	unknown	None	0	0	Has a trailer but needs to be renovated, applied for AHFC to get grants for housing.		no.	(1) Roof leaking (2) Water & Sewer (3) Broken Window	None	
St Mary's	557	0.1409	0	0	1	Building used for local VPO	(1) Replace furnace (2) Front Door (3) Broken window	Yes		None	
Stony River	16		0	0	0			No		Tribal Council serves as tribal court	
Toksook Bay	615	0.0308	0	1 + 1 on-call	0	TPO uses building		No	(1) Broken window (2) Electric service entrance broken (3) No plumbing	Nunakuyarmiut (Toksook Bay)- has a tribal court and tribal court judges, they are back tracking because it just recently started back up. They have Tribal Court Judges and an active children's code.	NO - shared office space
Tuluksak	500	0.1008	0	0	4	Renovated 2011/2012 use unknown, incomplete, needs improvement	(1) Foundation (2) Back door blocked (3) Poor lighting (4) Window	No		Established	
Tuntutuliak	450	0.0602	0	1 + 1 substitute	0	Renovated 2011/2012 TPO's uses the building	(1) Access ramp (2) Roller (3) Back Door	No		Has an active tribal court, has active Children's codes.	NO - using shared space
Tununak	327	0.0304	0	0	1	Unable to inspect interior; Used by VPO		No		"There was too many turn over so they started using Council Members as judges."	
Upper Kalskag	231	0.2304	0	0	0	Yes	(1) Broken Window (2) Hook up plumbing	Built 12x16 building some years ago, used for TDY VPSO, needs minor repairs		Active tribal court, not fully staffed	NO - sharing Tribal Council office

# UNIT 1 *Kotlik, Hamilton, Bill Moore's Slough*

## KOTLIK

640 polulation  
4.09% crimes per capita  
0 VPSOs  
0 TPOs  
1 VPOs



### Public Safety Building

1. Broken window
2. Entrance Door
3. Exit Door

### IT Infrastructure

The police department internet is going through the City Office.



# UNIT 1 KOTLIK



## Public Safety Housing

1. Raise building above flood level
2. Doors missing at bedrooms
3. Light Fixture Repair
4. Install flooring
5. Heating system service and repair



## UNIT 2 *Mountain Village, Pitka's Point, St. Mary's*

### MOUNTAIN VILLAGE


851 polulation

7.01% crimes per capita

0 VPSOs

0 TPOs

1 VPOs



#### Public Safety Housing

1. Broken window

#### Public Safety Building

Public Safety Office and Jail currently located at City Offices. New Facility is built but needs to be relocated due to being constructed over city utilities.


#### IT Infrastructure

The police department is located inside of the Tribal Council Office building, they have a DSL internet connection that is being provided by the tribe. No AVCP VPSO staff.

# UNIT 2 *Mountain Village, Pitka's Point, St. Mary's*

## PITKA'S POINT

125 polulation  
16% crimes per capita  
0 VPSOs  
0 TPOs  
0 VPOs



### Public Safety Building

Adequate

### IT Infrastructure

Unknown

### Public Safety Housing


None



# UNIT 2 *Mountain Village, Pitka's Point, St. Mary's*

## SAINT MARY'S

557 polulation  
14.09% crimes per capita  
0 VPSOs  
0 TPOs  
1 VPOs



### Public Safety Building

Building used is the city's old fire station and needs remodeling or replacement.


- 1. Furnace
- 2. Front door
- 3. Broken window

### IT Infrastructure

The police department has a cable modem, but no internet. A wireless antenna can be installed inside or outside pointing towards the tower that is right up the hill.

### Public Safety Housing

Exsisting, state unknown



## UNIT 3 *Aniak, Chuathbaluk, Crooked Creek, Georgetown, Lime Village, Upper Kalskag, Lower Kalskag, Red Devil, Napaimute, Sleetmute, Stony River*

### ANIAK


522 polulation

19.07% crimes per capita

0 VPSOs

0 TPOs

0 VPOs



### Public Safety Housing

Exsisting, state unknown

### Public Safety Building

New, unfinished.

1. Insulate Floor
2. Hook Up Plumbing
3. Insulate water and sewer lines

### IT Infrastructure


The Public Safety Office building was very nice and looked brand new. DSL looks to present, WIFI can also be utilized.



# UNIT 3 *Aniak, Chuathbaluk, Crooked Creek, Georgetown, Lime Village, Upper Kalskag, Lower Kalskag, Red Devil, Napaimute, Sleetmute, Stony River*

## CHUATHBALUK

*111 polulation*  
*Unknown crimes per capita*  
*0 VPSOs*  
*0 TPOs*  
*0 VPOs*



### Public Safety Housing


None

### Public Safety Building

None

### IT Infrastructure


Unknown



# UNIT 3 *Aniak, Chuathbaluk, Crooked Creek, Georgetown, Lime Village, Upper Kalskag, Lower Kalskag, Red Devil, Napaimute, Sleetmute, Stony River*

## UPPER KALSKAG

231 polulation  
23.04% crimes per capita  
0 VPSOs  
0 TPOs  
0 VPOs



### Public Safety Building

New Facility

1. Broken Window
2. Hook up plumbing

### IT Infrastructure

The Public Safety Office is a location that the tribe and village need to discuss if it is Upper or Lower. Did not see any internet equipment connected since the building was just moved to that location. A wireless antenna can be installed.

### Public Safety Housing

12x16ft, needs reparis



# UNIT 3 *Aniak, Chuathbaluk, Crooked Creek, Georgetown, Lime Village, Upper Kalskag, Lower Kalskag, Red Devil, Napaimute, Sleetmute, Stony River*

## LOWER KALSKAG

309 polulation

Unknown crimes per capita

0 VPSOs

1 TPOs

0 VPOs



### Public Safety Housing

Tribal housing could be used.

### Public Safety Building

New building could be used for Public Safety, but needs to be finished.

1. Partition walls
2. Cells
3. Doors and Windows

### IT Infrastructure


No public safety office building as of yet, when available, a wireless antenna can be installed.



**UNIT 3** *Aniak, Chuathbaluk, Crooked Creek, Georgetown, Lime Village, Upper Kalskag, Lower Kalskag, Red Devil, Napaimute, Sleetmute, Stony River*


**LIME VILLAGE**

*12 polulation*  
*unknown crimes per capita*  
*0 VPSOs*  
*0 TPOs*  
*0 VPOs*



**RED DEVIL**

*16 polulation*  
*0 crimes per capita*  
*0 VPSOs*  
*0 TPOs*  
*0 VPOs*



# UNIT 3 *Aniak, Chuathbaluk, Crooked Creek, Georgetown, Lime Village, Upper Kalskag, Lower Kalskag, Red Devil, Napaimute, Sleetmute, Stony River*

## SLEETMUTE

*92 polulation*  
*Unknown crimes per capita*  
*0 VPSOs*  
*0 TPOs*  
*0 VPOs*



### Public Safety Building

Very good condition, Tribal Office Building

### IT Infrastructure

VPSO met with Sleetmute tribe and discussed about future VPSO staff being located there. Exceed is the current internet provider, need to investigate if GCI can relate to a wireless antenna.

### Public Safety Housing

Next page



# UNIT 3 SLEETMUTE



## Public Safety Housing

1. Roof leak
2. Water and sewer
3. Broken window



## UNIT 4 *Akiachak, Akiak, Kwethluk, Tuluksak, Akiachak*

### AKIACHAK


*627 polulation*

*7.90% crimes per capita*

*0 VPSOs*

*5 TPOs*

*0 VPOs*



#### **Public Safety Housing**

Used by Chief of Police Department

#### **Public Safety Building**

Renovated 2011/12

Used by TPO

Unable to access building

#### **IT Infrastructure**

Did not see the location of the public safety building.

# UNIT 4 *Akiachak, Akiak, Kwethluk, Tuluksak, Akiachak*

## AKIAK

400 polulation  
8.03% crimes per capita  
0 VPSOs  
2 TPOs  
0 VPOs



### Public Safety Housing


Exsisting, state unknown

### Public Safety Building

1. Needs holding cells
2. Water and sewer needs turned back on
3. Porch and Stairs
4. Window

### IT Infrastructure


Current Jail is in the Tribal Council building with cages. The new location can be old library, this building is setup with data and telephone ports. The main office can be used as a data closet. If DSL is utilized, a wireless antenna can be installed outside pointing towards towers in the village.



# UNIT 4 *Akiachak, Akiak, Kwethluk, Tuluksak, Akiachak*

## KWETHLUK

751 polulation  
5.04% crimes per capita  
1 VPSOs  
3 TPOs  
1 VPOs



### Public Safety Building

<20 years-old

Used by VPSO & VPO

Renovations, requested

1. Boiler work
2. Reinforce cell door
3. Sewer line inspection
4. Foundation

### IT Infrastructure

Wireless Antenna is present in the police department.

### Public Safety Housing


Exsisting, state unknown



# UNIT 4 *Akiachak, Akiak, Kwethluk, Tuluksak, Akiachak*

## TULUKSAK

500 polulation  
10.08% crimes per capita  
0 VPSOs  
0 TPOs  
4 VPOs



### Public Safety Housing

None



### Public Safety Building

Needs improvments

1. Foundation
2. Back door blocked
3. Poor lighting
4. Window

### IT Infrastructure

The Tuluksak jail did not have any internet connection, I did not see any wireless antenna inside or outside. Wireless internet would be preferred. The wireless antenna can be installed inside by the front window or on the roof to be pointed towards the GCI tower.

# UNIT 5 *Napakiak, Napaskiak, Oscarville*

## NAPAKIAK


380 polulation

Unknown crimes per capita

1 VPSOs

2 TPOs

0 VPOs



### Public Safety Building

1. Window
2. Door lock
3. Exterior stairs

### IT Infrastructure

The wireless antenna is located inside of the main entrance conference area, that has wires going all throughout the building.

### Public Safety Housing


Exsisting, state unknown



# UNIT 5 *Napakiak, Napaskiak, Oscarville*

## NAPASKIAK

450 polulation  
3.00% crimes per capita  
0 VPSOs  
2 TPOs  
3 VPOs



### Public Safety Building

1. Front and back doors were set on fire
2. Foundation
3. Entry steps

### IT Infrastructure

The wireless antenna is located inside of the main office, the antenna is installed on the wall, it will have better service if installed right by the window and pointing towards the tower.

### Public Safety Housing

Exsisting, state unknown



# UNIT 6 *Atmautluak, Kasigluk, Nunapitchuk*

## ATMAUTLUAK

300 polulation  
5.04% crimes per capita  
0 VPSOs  
5 TPOs  
3 VPOs



### Public Safety Building

1. Window
2. Flooring
3. Chimney
4. Entry Stairs
5. Fuel leak

### IT Infrastructure

Wireless antenna should be utilized due to condition of building.

### Public Safety Housing

No housing availalbe



# UNIT 6 *Atmautluak, Kasigluk, Nunapitchuk*

## KASIGLUK

*600 polulation*

*3.04% crimes per capita*

*0 VPSOs*

*6 TPOs*

*0 VPOs*



### Public Safety Housing

No housing availalbe

### Public Safety Building

Inaccessible building


### IT Infrastructure

The wireless router is located outside, it is being pointed the wrong way from the tower, but still has internet connectivity.

# UNIT 6 *Atmautluak, Kasigluk, Nunapitchuk*

## NUNAPITCHUK

650 polulation  
7.02% crimes per capita  
0 VPSOs  
0 TPOs  
0 VPOs



### Public Safety Building

New, unoccupied

### IT Infrastructure

Wireless antenna should be utilized due to condition of building.

### Public Safety Housing


Unknown



# UNIT 7 *Kipnuk, Kongiganak, Kwigillingok, Tuntutuliak*

## KIPNUK

795 polulation  
3.04% crimes per capita  
0 VPSOs  
3 TPOs  
0 VPOs



### Public Safety Building

1. Foundation
2. Broken windows
3. Meter base service wire

### IT Infrastructure

Wireless antenna should be utilized due to condition of building.

### Public Safety Housing


Existing, state unknown



# UNIT 7 *Kipnuk, Kongiganak, Kwigillingok, Tuntutuliak*

## KONGIGANAK

657 polulation  
3.01% crimes per capita  
0 VPSOs  
5 TPOs  
0 VPOs



### Public Safety Building

1. No Heat
2. No Running Water
3. Broken Windows

### IT Infrastructure

Wireless Antenna is present in the police department

### Public Safety Housing

Exsisting, state unknown



# UNIT 7 *Kipnuk, Kongiganak, Kwigillingok, Tuntutuliak*

## KWIGILLINGOK


*321 polulation*

*2.02% crimes per capita*

*0 VPSOs*

*4 TPOs*

*3 VPOs*



### Public Safety Housing

None

### Public Safety Building

New

### IT Infrastructure


The police department building has a DSL internet connection, with a 4port router.



# UNIT 7 *Kipnuk, Kongiganak, Kwigillingok, Tuntutuliak*

## TUNTUTULIAK

450 polulation  
6.02% crimes per capita  
0 VPSOs  
2 TPOs  
0 VPOs



### Public Safety Building

1. Access Ramp
2. Boiler
3. Back door

### IT Infrastructure

The Public Safety Office building did not have any internet. A wireless antenna would be preferred, the antenna can be installed on the roof or inside by a window pointing towards a GCI tower.

### Public Safety Housing


None



# UNIT 8 *Chefornak, Mekoryuk, Newtok, Nightmute, Toksook Bay, Tununak, Umkumiut*

## CHEFORNAK

500 polulation  
3.05% crimes per capita  
0 VPSOs  
2 TPOs  
0 VPOs



### Public Safety Building

1. Electrical panel/meter base
2. Plumbing
3. Front entrance deck and stairs
4. Broken window

### IT Infrastructure

Wireless Antenna is present in the police department.

### Public Safety Housing

Next page




# UNIT 8

## CHEFORNAK

### Public Safety Housing


1. Exposed electrical wire
2. Foundation
3. Fuel tank stand
4. Missing chimney cap



# UNIT 8 *Chefornak, Mekoryuk, Newtok, Nightmute, Toksook Bay, Tununak, Umkumiut*

## MEKORYUK

212 polulation  
5.05% crimes per capita  
1 VPSOs  
3 TPOs  
0 VPOs



### Public Safety Building

New building. Needs plumbing hooked up.

### IT Infrastructure

The police department building has a wireless antenna that is located outside, and a 4 port Net Gear router.

### Public Safety Housing

None



# UNIT 8 *Chefornak, Mekoryuk, Newtok, Nightmute, Toksook Bay, Tununak, Umkumiut*

## NEWTOK


*374 polulation*

*4.05% crimes per capita*

*0 VPSOs*

*0 TPOs*

*3 VPOs*



### **Public Safety Housing**

None

### **Public Safety Building**

Using village council office-space room


### **IT Infrastructure**

Unknown

# UNIT 8 *Chefornak, Mekoryuk, Newtok, Nightmute, Toksook Bay, Tununak, Umkumiut*

## NIGHTMUTE

316 polulation  
1.03% crimes per capita  
0 VPSOs  
0 TPOs  
1 VPOs



### Public Safety Building


1. No running water
2. No heat
3. Electrical panel/meter base service wire

### IT Infrastructure

The public safety office was being utilized, did not see a wireless antenna.

### Public Safety Housing


None



# UNIT 8 *Chefornak, Mekoryuk, Newtok, Nightmute, Toksook Bay, Tununak, Umkumiut*

## TOKSOOK BAY

615 polulation  
3.08% crimes per capita  
0 VPSOs  
3 TPOs  
0 VPOs



### Public Safety Building


1. Broken Window
2. Electric service
3. Entrance broken
4. No plumbing

### IT Infrastructure

Public Safety Office has DSL connection. A wireless antenna can be used when and if more VPSO staff are located there in the future.

### Public Safety Housing


None



# UNIT 8 *Chefornak, Mekoryuk, Newtok, Nightmute, Toksook Bay, Tununak, Umkumiut*

## TUNUNAK

327 polulation  
3.04% crimes per capita  
0 VPSOs  
0 TPOs  
1 VPOs



### Public Safety Building

New building. No one available for interior inspection.

### IT Infrastructure

The Public Safety Office building was not assessed due to no entry of the building and did not see any type of internet equipment outside.

### Public Safety Housing


None



# UNIT 9 *Chevak, Hooper Bay, Paimiut, Scammon Bay*

## CHEVAK

1064 polulation  
3.00% crimes per capita  
0 VPSOs  
0 TPOs  
12 VPOs



### Public Safety Building

Renovated in 2011/12.

Used by VPOs

1. Boiler Service and/or Replacement (2 new boilers located in crates under building)
2. Electrical Panel Service and Repair
3. Exterior Hand Railing Repair


### Public Safety Housing

Existing, state unknown



### IT Infrastructure


Wireless Antenna is present in the police department.



# UNIT 9 *Chevak, Hooper Bay, Paimiut, Scammon Bay*

## HOOPER BAY

1200 polulation  
8.08% crimes per capita  
0 VPSOs  
0 TPOs  
4 VPOs



### Public Safety Building

1. Sewer line replacement
2. Miller Furnace (Heater) maintenance
3. Broken windows and doors
4. Replace rear entry steps
5. Foundation level, repair, and/or replacement

### Public Safety Housing

Existing, state unknown

### IT Infrastructure


The wireless antenna is located outside.



# UNIT 9 *Chevak, Hooper Bay, Paimiut, Scammon Bay*

## SCAMMON BAY

600 polulation  
5.03% crimes per capita  
1 VPSOs  
0 TPOs  
0 VPOs



### Public Safety Building

1. Level/Replace Foundation
2. Inadequate Size for Personnel and Equipment
3. Electric Unit Heater Hazard
4. Building Separating at prior addition
5. Broken Windows

### Public Safety Housing

None

### IT Infrastructure


The wireless antenna is located outside.



# UNIT 10 *EEK, Goodnews Bay, Platinum, Quinhagak*

## EEK

*396 polulation*  
*4.04% crimes per capita*  
*1 VPSOs*  
*1 TPOs*  
*1 VPOs*



### Public Safety Building

1. Foundation
2. Uninsulated floor
3. Broken window

### IT Infrastructure

Wireless Antenna is recommended

### Public Safety Housing


None



# UNIT 10 *EEK, Goodnews Bay, Platinum, Quinhagak*

## GOODNEWS BAY

*253 polulation*  
*3.08% crimes per capita*  
*1 VPSOs*  
*0 TPOs*  
*0 VPOs*



### Public Safety Housing


None

### Public Safety Building

Good condition

### IT Infrastructure


The public safety office will be receiving a wireless antenna. The antenna that was there was taken out due to malfunction of the device.



# UNIT 10 *EEK, Goodnews Bay, Platinum, Quinhagak*

## PLATINUM

*64 population*  
*8.09% crimes per capita*  
*0 VPSOs*  
*0 TPOs*  
*0 VPOs*



### Public Safety Housing

None

### Public Safety Building

No adequate building

### IT Infrastructure


None



# UNIT 10 *EEK, Goodnews Bay, Platinum, Quinhagak*

## QUINHAGAK

*699 polulation*  
*5.00% crimes per capita*  
*0 VPSOs*  
*6 TPOs*  
*0 VPOs*



### Public Safety Housing

Exsisting, state unknown

### Public Safety Building

Brand new building waiting for inspection.

### IT Infrastructure

Has a nice police department, brand new building. Wireless would be ideal for the VPSO staff, since there will be other departments like Troopers and Alaska Court System.



# UNIT 12 *Marshall, Ohogamiut, Pilot Station, Russian Mission*

## MARSHALL

440 polulation  
7.05% crimes per capita  
0 VPSOs  
0 TPOs  
1 VPOs



### Public Safety Housing


Exsisting, state unknown

### Public Safety Building

1. Broken/missing windows
2. Foundation Repair/Replace
3. Roof Metal Repair/Replace
4. Electrical Hazards
5. Heater Service/Replacement

### IT Infrastructure

The police department looked to be abandoned, there was a cable modem, which was probably their internet connection. Did not see wireless antenna.



# UNIT 12

Marshall, Ohogamiut, Pilot Station, Russian Mission

## PILOT STATION


651 polulation

3.06% crimes per capita

0 VPSOs

0 TPOs

3 VPOs



### Public Safety Building

1. Broken/missing windows
2. Broken/missing doors
3. Repair/replace Exterior Handrails
4. Needs finish flooring

### IT Infrastructure

The wireless antenna is located outside towards the back of the police department.

### Public Safety Housing

Next page




# UNIT 12

## PILOT STATION

### Public Safety Housing


1. No stairs at second exit
2. Electrical Panel Cover
3. Entry Door Finish



# UNIT 12 *Marshall, Ohogamiut, Pilot Station, Russian Mission*

## RUSSIAN MISSION

331 polulation  
11.09% crimes per capita  
0 VPSOs  
0 TPOs  
0 VPOs



### Public Safety Building

- 1. Gable End Metal Missing

### IT Infrastructure

There is no AVCP VPSO staff, did not see the public safety building, for that area a wireless antenna can be installed when a staff member is located there.

### Public Safety Housing

Exsisting, state unknown

# UNIT 13 *Alakanuk, Chuloonawick, Emmonak, Nunam Iqua*

## ALAKANUK

734 polulation  
4.30% crimes per capita  
0 VPSOs  
0 TPOs  
0 VPOs



### Public Safety Building

1. Heater Repair/replace
2. Foundation repair/replace
3. No running water
4. Leaking fuel line
5. Soffit missing
6. Broken Windows and Doors
7. Electrical Panel Service and Cover

### IT Infrastructure

The building is not safe; a wireless antenna is outside on the roof with a data cable going down the chimney that is connected to a net gear router.

### Public Safety Housing

Next page



# UNIT 13

## ALAKANUK

### Public Safety Housing

1. Front stairs and deck
2. Windows broken
3. Ground Rod
4. Foundation



# UNIT 13 *Alakanuk, Chuloonawick, Emmonak, Nunam Iqua*

## EMMONAK

*1020 polulation*


*18.00% crimes per capita*

*2 VPSOs*

*0 TPOs*

*1 VPOs*

*One VPSO works in the daytime and responds to nearby villages. The second VPSO covers graveyard shifts. There are at least three Alaska State Troopers that work 2-weeks on and 2-weeks off.*



### Public Safety Building

1. Broken front door glass
2. Exterior paint

### IT Infrastructure

Wireless Antenna is present in the police department.




### Public Safety Housing

Exsisting, state unknown

# UNIT 13 *Alakanuk, Chuloonawick, Emmonak, Nunam Iqua*

## NUNAM IQUA

*196 polulation*  
*4.05% crimes per capita*  
*0 VPSOs*  
*0 TPOs*  
*0 VPOs*



### Public Safety Building

1. Mold and Foul Odor
3. Extensive water damage
4. Foundation and Stairs

(Photos continued on following page.)

### IT Infrastructure

The police department is not suitable for VPSO staff or incarcerated individuals.




### Public Safety Housing

Exsisting, state unknown

# UNIT 13

## NUNAM IQUA

Public Safety Facility  
Continued





**AVCP.ORG**

PO BOX 219 BETHEL, AK 99559 | 1 800 478 3521